



# HALL Technical Services, LLC

## PCA INLET ADAPTER - NYLON

"The GSE Problem Solvers"



Molded EPDM Gasket is service proven to last for years.

Stainless Steel screen insert to keep debris from entering aircraft.

### FEATURES

- Complete Assembly Part #IA-8980-N
- PCA 8" Adapter/ Connector
- Fits ATA Standard Flange
- Fits Standard 8" Hose
- High impact resistant polymer
- Impact tested for durability
- Rotary Cam Action Latch Handles
- No exposed linkages, springs, or bolts
- Eliminates FOD
- Minimizes moving parts
- Molded EPDM Gasket
- Weighs less than 5 pounds
- Protects duct from damage
- 1-year Warranty on Latch Handle Casting

### COMPONENTS

#### Hall Part #8980-2-100K

##### Handle Housing Replacement

Fits right or left side, includes (2) bolts, (2) Nord-Lock washer sets and Rubber Grip Handle

#### Hall Part #8980-2-200P

##### Base Ring Assembly with Gasket

Includes the gasket attached to the base



The word "LOCK" is cast into the handles. Provides added safety as ramp service staff can check locked position.



Rotary Cam Action Latch Handles with Slot Filling Latch.

For more information please visit us online at [www.halltechservices.com](http://www.halltechservices.com), call us at 724.824.7100, or email us at [info@halltechservices.com](mailto:info@halltechservices.com)



## PCA INLET ADAPTER - ALUMINUM

"The GSE Problem Solvers"



Molded EPDM Gasket is service proven to last for years.



Stainless Steel screen insert to keep debris from entering aircraft.

### FEATURES

- Complete Assembly Part #IA-8980
- PCA 8" Adapter/ Connector
- Fits ATA Standard Flange
- Fits Standard 8" Hose
- Rotary Cam Action Latch Handles
- No exposed linkages, springs, or bolts
- Eliminates FOD
- Minimizes moving parts
- Molded EPDM Gasket
- Weighs less than 5 pounds
- Protects duct from damage
- 1 year warranty on Latch Handle Casting
- US Patent No. 6289949

### COMPONENTS

#### Hall Part #8980-2-100K

#### Handle Housing Replacement

Fits right or left side, includes (2) bolts, (2) Nord-Lock washer sets and Rubber Grip Handle

#### Hall Part #8980-2-200

#### Base Ring Assembly with Gasket

Includes the gasket attached to the base



The word "LOCK" is cast into the handles. Provides added safety as ramp service staff can check locked position.



Rotary Cam Action Latch Handles with Slot Filling Latch.

For more information please visit us online at [www.halltechservices.com](http://www.halltechservices.com), call us at 724.824.7100, or email us at [info@halltechservices.com](mailto:info@halltechservices.com)